

Missing Parts (Lam SP-323)	
parts名	数量
IWAKI Damper PUMP/2022020-00 2nd source:PDA-40H1	2
SP323 Chuck Unit /2305255-02	2
DV DOUBLE ECO-GRIPPER FO/2310992-06 FLIPPER 12"	2
MOTHER BOARD PIII/1.26GHZ/2314735-00 512MB ASSEMBLY	1
EQUIPE ROBOT ATM 407C-2/2200874-00 CE COC 6-0000-38	1
CONTROLLER ESC-200 FOR ROBOT/2007340-00	1
SP323 Elevator driver/846-106227-001 SERVO 400W R88D-UA12V (YASKAWA)	2
SP323 PC BOARD 9ISA/2341524-00 backplane, passive/9ISA/	1
SP323 chuck spindle CH-B/2022348-02	2
SP323 ECO Clamp ring/2014898-00	12
SP323 MED heater(LAUDA)/2304919-00 2,3KW/2	2
Elevator Driver/2008936R00 OMRON R88D-UA12V 400W	2
L/P frame node board/2337542-01 WKZ02	4
L/P CPU board/2363555-00 WKZ02	4
Isoport dock/undock motor/2342272-00	4
Retrofit Kit f. Disp.Motor/2320023-00 Dispenser Motor	4