

LTXC ASL3000 Tester System Configuration

Tester No.	3
Tester Serial Number	
Tester Owner	
ASSET NO.	161210000042 161215000030
Income	2014.04.22
Host ID	
O/S	WinXP&Win2K
VisualATE software	6.2
IP address	10.185.146.210
System Type	ASL3K(RF)
PIN CHANNELS	
Remark	RF16 ports
Location	

MVNA

Front

After

Name	Part Number	Name	Part Number
RF BASB	671-4575	MVNA clock	674-4556
RF BASB	671-4575		
RF BASB	671-4575		
RF BASB	671-4575		
RF IQ Source	672-6129	2nd LO distribution	671-4488
RF Control	671-4601		
BASB	672-6141	2nd dwon converter noise	671-5319
BASB	672-6141		
BASB	672-6141	2nd dwon converter noise	671-5319
BASB	672-6141		
BASB IQ Source	672-6139		

RF break module cal fail

3					
Slot Assignment		REV	GPIB		
Slot 1	OVI	C	13	POWER METER	
Slot 2	OVI	C			
Slot 3	OVI	C	25	LO	SMIQ06B
Slot 4			26	RF1	SMIQ06B
Slot 5			27	RF2	SMIQ06B
Slot 6	TMU	A	28	RF3	SMIQ06B
Slot 7					
Slot 8					
Slot 9	DVI-300	G			
Slot 10					
Slot 11	DVI-2K	H			
Slot 12					
Slot 13	DVI-2K	H			
Slot 14					
Slot 15					
Slot 16					
Slot 17					
Slot 18					
Slot 19	OVI	C			
Slot 20	MUX	A			
Slot 21					
Slot 22	TIB				
Slot 23	MDI				
Slot 24					
Slot 25					
Slot 26					
Slot 27	CLK4				
Slot 28	BTB				
Slot 29					
Slot 30					
Slot 31					
Slot 32					

OVI BN:671-3230
 TMU BN:671-5333
 DVI300 BN:671-4678
 DVI2K BN:678-6172
 MUX BN:671-4534
 MDI BN:671-4534
 CLK4 BN:672-6135
 BTB BN:671-5366